



33 South La Patera Lane
Santa Barbara, CA 93117-3214
ph (805) 681-3300
fax (805) 681-3311
tech@motioneng.com
www.motioneng.com

ERRATA: APPLICATION NOTE 218 REV. A, DCO 1295

Receptacles J8-11 and J12-15 on XMP-PULSE-PCI Controller Boards (PCB Revision 1.0)

Note that currently configured PCB Revision 1.0 XMP-PULSE-PCI-MAIN-16 main controller boards (Part No. A040-0011), and XMP-PULSE-PCI-EXP-16 expansion boards (Part No. A041-0011), jumpers are shipped with VHDCI receptacles **J8-11** and **J12-15** switched. Information contained in Application Note 218, Rev. A describes VHDCI pin-outs for the original design specification, *not* the current configuration.

The diagram below shows J8-11 and J12-15 in their current configuration.

